

[illegible]

foot long pressure treatment vessel that the previous owner claims is still half full of creosote. - The company used Creosote, Pentachlorophenol (PCP), and Copper Chromate Arsenic (CCA) to treat wood. - The request for assistance from the RCRA program is to sample and gauge the tanks and vessels to determine the nature and volumes of each. - (Carroll, x2220)

Formatted: Font (Default) Arial

**WOOD INDUSTRIES, SAN ANTONIO, TX:** - During the week of June 19, 2017, a member of the Region 6 EPA Emergency Management Branch (EMB) member will conduct a site visit at this site. This site was referred to EMB by the Region 6 EPA Resource Conservation and Recovery Act (RCRA) program through the Texas Commission on Environmental Quality (TCEQ). - The Walker Wood Treater site, in Livingston, TX, has 14 tanks in the tank farm ranging up to 30,000 gallons in size (contents and volumes unknown) and a 92 foot foot long pressure treatment vessel that the previous owner claims is still half full of creosote. - The company used Creosote, Pentachlorophenol (PCP), and Copper Chromate Arsenic (CCA) to treat wood. - The request for assistance from the RCRA program is to sample and gauge the tanks and vessels to determine the nature and volumes of each. (Carroll, x2220)

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial, Not Italic

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

**FJ DOYLE SALVAGE, LEONARD, TX:** - During the week of June 19, 2017, a member of the Region 6 EPA Emergency Management Branch (EMB) member will conduct a site visit at this site. This site was referred to EMB by the Region 6 EPA Resource Conservation and Recovery Act (RCRA) program through the Texas Commission on Environmental Quality (TCEQ). - The F.J. Doyle Salvage facility in Leonard salvaged electrical transformers which lead to polychlorinated biphenyls (PCBs) contamination in the soil. - (Carroll, x2220)

Commented [PM2]: These two inputs are the same. I will delete the one that shows San Antonio.

Formatted: Font (Default) Arial

Formatted: Space After: 0 pt, Line spacing: single

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial, Not Italic

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

**US COOLING TOWERS, PLANVIEW, TX:** - During the week of June 19, 2017, a member of the Region 6 EPA Emergency Management Branch (EMB) member will conduct a site visit at this site. This site was referred to EMB by the Region 6 EPA Resource Conservation and Recovery Act (RCRA) program through the Texas Commission on Environmental Quality (TCEQ). - The US Cooling Towers Site in Plainview is a former manufacturer at which chromium and arsenic have been found in surface soil samples. - The area surrounding the facility is mixed industrial, residential and agricultural. - (Carroll, x2220)

Formatted: Font (Default) Arial

Formatted: Space After: 0 pt, Line spacing: single

Formatted: Font (Default) Arial, No underline

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

**EXTREME METAL FINISHING, EMORY, TX:** - The Texas Commission on Environmental Quality (TCEQ) Removal Program requested an EPA On-Scene Coordinator (OSC) attend a TCEQ Austin/TCEQ Tyler site walk-through at the Extreme Metal Finishing site in Emory, Texas on June 15, 2017. - The site was recently referred to TCEQ Removal Program from TCEQ Enforcement Division. - The Texas Office of the Attorney General has determined that enforcement efforts have been exhausted at the site. - (Carroll, x2220)

Formatted: Font (Default) Arial

**2017 NATIONAL RESPONSE TEAM/REGIONAL RESPONSE TEAM (NRT/RRT) CO-CHAIRS NATIONAL MEETING, PITTSBURGH, PA:** - Emergency Management Branch

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial, No underline

Formatted: Font (Default) Arial

staff participated in the National Response Team (NRT)/Regional Response Team (RRT) Co-Chairs meeting in Pittsburgh, PA on June 12, 13, 14, 2017. (Carroll, x2220)

**STAFFORD ACT WEBINAR, DALLAS, TX:** On June 20, 2017, Emergency Management Branch (EMB) staff, along with staff from EPA HQ Office of Emergency Management (OEM), and Regions 2 and 7 will co-lead a national webinar training on the Stafford Act/Mission Assignments. The target audience for this course include EPA Regional and HQ personnel who might staff the Emergency Support Function (ESF) #10 desk at the Federal Emergency Management Agency Joint Field Office (JFO), Regional Response Coordination Center (RRCC), or the National Response Coordination Center (NRCC); and EPA On-Scene Coordinators (OSCs) who might participate in a Stafford Act ESF #10 response. Hurricane season has officially started begun, and this training will better prepare EPA response personnel in the event Region 6 is impacted by a storm this year. (Carroll, x2220)

**SPIKE DRILLING TANK BATTERY OIL SPILL RESPONSE, DAMON, FORT BEND COUNTY, TEXAS:** On June 9, 2017, EPA was notified by a Texas Parks & Wildlife Game Warden of an oil discharge in Fort Bend County, TX. The discharge of 130 barrels (bbls) of oil and 130 bbls of produced water was reported to have occurred Sunday, June 4, 2017 in Fort Bend, TX. Over five miles of Cow Creek, a tributary of the Brazos River, was impacted. Cow Creek is a tributary of the Brazos River. The Responsible Party is reported as Spike Drilling. Spike Drilling is reported as the Responsible Party. The discharge was not reported to the National Response Center (NRC). The spill occurred through a failed fitting on the bottom of one of the produced water tanks. The tank battery consists of four tanks, two produced water and two oil tanks and does not appear to have secondary containment. (Carroll, x2220)

**CWA 311 SPILL PREVENTION CONTROL AND COUNTERMEASURE (SPCC) AND FACILITY RESPONSE PLAN (FRP) INSPECTIONS CONDUCTED IN CORPUS CHRISTI, TX:** On June 13, 2017, two Emergency Management Branch (EMB) Inspectors conducted SPCC and FRP Inspections of the NuStar Corpus Christi facility located at 3009 W Causeway Blvd in Corpus Christi, TX. The Inspections were scheduled as part of the FRP Approval Process and was targeted as part of the Texas Environmental Collaborative Action Plan. (Carroll, x2220)

**CWA 311 SPILL PREVENTION CONTROL AND COUNTERMEASURE (SPCC) AND FACILITY RESPONSE PLAN (FRP) INSPECTIONS CONDUCTED IN CORPUS CHRISTI, TX:** On June 13, 2017 two Emergency Management Branch (EMB) Inspectors conducted SPCC and FRP Inspections of the Kirby Inland Marine Corpus Christi Facility located at 3105 E. Navigation Blvd. in Corpus Christi, TX. The Inspections were scheduled as part of the FRP Approval Process and was targeted as part of the Texas Environmental Collaborative Action Plan. (Carroll, x2220)

**CWA 311 SPILL PREVENTION CONTROL AND COUNTERMEASURE (SPCC) AND FACILITY RESPONSE PLAN (FRP) INSPECTIONS CONDUCTED IN CORPUS**

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Space After: 0 pt

Formatted: Font (Default) Arial, No underline

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Space Before: 0 pt

Formatted: Font (Default) Arial, No underline

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial, No underline

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial, Bold

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial, Bold, No underline

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial



**SPILL PREVENTION CONTROL AND COUNTERMEASURE (SPCC) AND FACILITY RESPONSE PLAN (FRP) INSPECTIONS INSPECTOR TRAINING COURSE DALLAS, TX**

Region 6 will host Spill Prevention and Facility Response Plan (SPCC and FRP) Inspector Training for EPA and Tribal Inspectors from around the Nation on from June 26 — 30, 2017. The course will be taught-instructed by EPA staff from the Office of Emergency Management along with senior regional inspectors. The training is designed to meet Agency requirements under EPA Order 3500.1, "Training and Development for Compliance Inspectors/Field Investigators." The 40-hour course is a program-specific training requirement for oil inspectors, other EPA personnel (such as On-Scene Coordinators (OSCs), conducting compliance monitoring activities associated with 40 CFR part 112 (such as oil inspections or Government Initiated Unannounced Exercises (GIUEs)). The training will be conducted in the Region 6 Office. (Carroll, x2220)

Formatted: Font (Default) Arial, Not Italic

Formatted: Font (Default) Arial, No underline

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial

Formatted: Font (Default) Arial, Not Italic

Formatted: Font (Default) Arial

Formatted: Space After: 0 pt, Line spacing: single